JAN 3 2000

Filed under Remonumentation Act 345 of 1990 LIBER 1 PAGE 372

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF KICHIGAN **LEHAWEE COUNTY** FILED

	Filling Iveda	Michigan or years of	
SECTION			7 DEC 1999 1:02:41 FM
For corners in Lenawee (County)	Located In:	Corner Code #	VICTORIA I, DANIELS REDISTER OF DEEDS
1. Public Land Survey	T <u>-6 - S</u> R <u>- 3 - E</u> T R R T R R		
Property Controlling S	T R T R T R T R R T R R T R T R T R T R		Register of Deeds Stamp & File Number
4. Lot No, Recorder 5. Private Claims I. Glenn E. Richard do hereby certify that under requirem in lines 1 and 2 above were in conformance with the Court of Law, established, re-est expressed below: NOTE: Not more than 4 corn on this certificate. A. Description of original mo This position not est 1951 Walter Frazie South 1/4 line 1975 I set a R.R. st by Walter Frazie at 1991 Werner Somr	nents of P.A. 74, Michigan P formance with regulations as of the United States Depart of Law and/or that the control of the Michigan Boardstablished, monumented, refers, all in the same to nument and accessories ablished by original gord did a lot survey in the pike in the pavement of	survey on November 16, 19 99, A. of 1970, the corner points mentioned arthern of the Interior, Bureau of Land riner points mentioned in lines 3, 4 and 5 d of Land Surveyors or by a Decree of a re-monumented, recovered, found as with and range, may be recorded and/or subsequent restoration: Divernment surveyors, e SW 1/4 of Sec. 32 that called on a line between East and West 3, Page 377	A B C D E F G H I J K L M 1 2 3 4 4 5 6 18 7 6 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 33 34 35 36 36 11 12 31 13 for the east line of the lot as being the North 8 11/4 corners and by retracing the 1951 survey 8 377
/			

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Nov. 12, 1999 I staked location for contractor to set monument box in new asphalt pavement. Nov. 16, 1999 I set a 5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040 in the monument box at the location of the previous recordings.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

Fd. P.K. nail & tag stamped 16034 in T.P. S 2° W 59.34 Fd. P.K. nail & tag stamped 16034 in 6" Cedar S 60° W 129.88 Fd. 1/2" rod in concrete monument South 98.53 1/2" rod South 61.43 Back of curb 3.3 east of curb inlet North 11.88 Fd split seam iron set by Walter Frazier in 1951 South 60.81

STANDARD OF MICHIGAN WHE OF MICHIGAN GLENN E. RICHARD No. 13040 SE JONAL STA WALL WALLER

	Manual Marie
	Co. Rep Henne Pular Date November 23, 1999
Signed by Glann & Richard Da Glenn E. Richard	ate Dec. 1, 1999
Surveyor's Michigan License No. 13040	Form approved by Michigan State Board of Land

REVISED MAY 14, 1975