

DEG 2 2 1998

SECTION

Filed under Remonumentation Act 345 of 1990

## LIBER 1 LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

PAGE 307 STATE OF MICHIGAN LENAWEE COUNTY FILED

For corners in  Lenawee (County)	Located In:	Corner Code #	16 DEC 1998 4:20:52 PN
1. Public Land Survey	T <u>-6 - S</u> R <u>- 3 - E</u> T R T R	<u>G - 12</u>	VICTORIA J. DANIELS REGISTER OF DEEDS
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec</li> </ol>	T R S T R S T R S T R R S T R		Register of Deeds Stamp & File Number
4. Lot No, F 5. Private Claims	ecorded Plat		A B C D E F G H I J K L M
do hereby certify that under in lines 1 and 2 above were current manual of survey ins Management or by a decree of above were in conformance	, in a field so requirements of P.A. 74, Michigan P. in conformance with regulations a tructions of the United States Depart of a Court of Law and/or that the conwith the rules of the Michigan Board, re-established, monumented, re-	A. of 1970, the corner points mentic and rules therefore as required in Atment of the Interior, Bureau of L and points mentioned in lines 3, 4 and a of Land Surveyors or by a Decree	ned the 6 18 17 16 15 14 13 and 7 and 5 8 19 20 21 22 23 24 of a as 9 10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			ed 11 12 31 32 33 34 35 36

Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1824, John Mack Set 1/4 Sec. post B. Oak 6 N 59 W 34, Leverwood 5 S 22 E 24 Early 1900's J.L. Richard's record calls for "Stone on end surrounded by others" and 1940's same record as above by Harold Clegg

1935 Point of beginning for Assessor's Plat No. 15, City of Adrian

1948 Point of beginning for Woodlawn Farm

1965 I found a spike, point of beginning for Plat of Rolling Meadows

1998 George Avendt P.S. No. 16034 dug found iron pipe and raised to surface with 1/2" X 18" iron rod and Lawrence Feindt recorded it in L5 P370

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

November 5, 1998, Found 1/2" X 18" iron pipe capped 16034 at surface of pavement, in top of 3/4" X 20" iron pipe. Replaced found iron pipe with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 and set monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod in monument box with Lenawee County Re-mon cap stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Found plat monument North 33.00



NW. corner brick apartment building S 25° E 65.29 Fd. nail in S. face of Elec. pole N 25° W 23.42 Fd. nail in SW. face of 23" Maple N 25° E 42.23	GLENN E. RICHARD NO. 13040 G
Ratified by Peer Group in accordance with P.A. 345 Co. Republicant Signed by Alban E. Richard Date	Chiland Date December 1, 1998
Surveyor's Michigan License No. <u>13040</u>	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 10 REVISED MAY 14, 1 REVISED JAN., 1 ADAPTED FOR WORD PROCESSING MARCH, 1