DEC 2 2 1998

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN LENAUFF COUNTY

| For   | corners in  |   |   | FILED  |  |  |
|---|---|---|---|--|--|--|
| <u>. ا</u>                                    | <u>enawee</u>   | Located In: Adrian Twp.   | Corner Code #   |  |  |  |
|   | (County)  |   |   | 16 DEC 1998 4:21:04 PM                                   |  |  |
| 1. 1  | <sup>o</sup> ublic Land Survey  | T <u>- 6- S</u> R <u>-3- E</u><br>T R<br>T R  | H-12  | VICTORIA J. DANIELS<br>REGISTER OF DEEDS                 |  |  |
| 3.  | Property Controlling S In Section S Miscellaneous S Property in Sec S   | T R T R T R T R T R T R T R T R T R T R   |   | Register of Deeds Stamp & File Number                    |  |  |
| 4. {<br>5. {                                  | ot No, Record   | ed Plat   |   | A B C D E F G H I J K L M                                |  |  |
| do )<br>in lii<br>curre<br>Man<br>abov<br>Cou | nes 1 and 2 above were in con<br>ent manual of survey instructions<br>agement or by a decree of a Cou<br>le were in conformance with the  | , in a field survey ments of P.A. 74, Michigan P.A. of a formance with regulations and rus of the United States Department of Law and/or that the corner por rules of the Michigan Board of Law and monumented, re-monumented, re-monumented. | ules therefore as required in the at of the Interior, Bureau of Land points mentioned in lines 3, 4 and 5 and Surveyors or by a Decree of a | 4  |  |  |
| NO <sup>-</sup>                               | FE: Not more than 4 corn on this certificate.   | ers, all in the same town an  | nd range, may be recorded   | 11<br>12<br>13<br>13<br>31<br>32<br>33<br>34<br>35<br>36 |  |  |
| Α.  | G.L.O. This position<br>1904 James Blair ca<br>Early 1900's J.L. Ric<br>1935 The corner is s<br>1936 The corner is s<br>1965 Point of beginn  | hown on Assessor's Plat No<br>shown on Assessor's Plat N<br>ning, Plat of West Maplewo  | I government surveyors<br>square hole in same"<br>lair's with note "corner is 7. I<br>o. 15, City of Adrian<br>lo. 17, City of Adrian       | -  |  |  |
| ₿.  | Description of corner evidence found and/or method applied in restoring or reestablishing corner:   |   |   |  |  |  |
|   | Found 3/4" X 19" iron pipe 18" deep in water valve box. Dug out the valve box and probed but didn't find any stone. Set a monument box and 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 at location of the found iron pipe. |   |   |  |  |  |
| C.  | Description of monument t   | for corner and accessories es   | tablished to perpetuate locating  | the position of the corner                               |  |  |

5/8" X 3' re-rod in monument box with Lenawee County Re-mon cap stamped P.S.13040.

This position not established by original government surveyors. This monument is accepted as the best available evidence of the position on the corner.

Fd. Iron pipe South 33.00 Fd. dbl. hd. nail & disc in Elec. pole N 25° E 80.74

Fd. dbl. hd. nail & disc in Tel. pole S 40° E 33.15

Fd. dbl. hd. nail & disc in Elec. pole S 75° W 59.34

Fd. dbl. hd. nail & disc in E. side 22" Ash S 10° W 23.68

Fd. iron pipe N 45° E 46.20

STATE OF MICHIQUE GLENN E. RICHARD No. 13040 ASSIONAL ST ONAL CONAL

| Ratified by Peer Group in accordance with P.A. 34 | 5 Co. Rep Slenne Richard | Date December 1, 1998                    |
|---|--------------------------|--|
| Signed by <u>Alan C. Ruffard</u> Glenn E. Richard | Date Dec. 11, 1998       |  |
| Glenn E. Richard                                  |                          |  |
| Surveyor's Michigan License No. <u>13040</u>      |                          | FORM APPROVED BY MICHIGAN STATE BOARD OF |