SURVEY & REMONUMENTATION

FEB 1 6 1999

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE I PAGE 289

Filing Requirement of Act 74, Mich. P.A. 1970

PAGE 207 STATE OF MICHIGAN LENAWEE COUNTY

ABCDEFGHI

6

1

7

8

10 11

12

13

JKLM

SECTION

4. Lot No.

5. Private Claims

Miscellaneous S T R R Register of Deeds Stamp & File Number

	_							
				•				
 Glenn E. Ric 	hard			in a field su	rvey on Oc	tober :	16 . 1998	
do hereby certify		requiremente	of D A 7/ 8/	lichigan D A	of 1070 H	o corne	nointe me	tioned
in lines 1 and 2:	above were	in conforma	ance with rec	ulations ar	ad rules the	refore a	s required	in the

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO 1815 Alexander Holmes, set post Cor. Sec.'s 31 & 32, Elm 9 N 45 E 6, Lynn 12 S 10 E 10 1880 James Blair found stake and stone

Recorded Plat

1883 James Blair found corner

1919 J.L. Richard surveyed Blissfield Hwy and called for the corner "stake" being 7' right (East) of center line

1954 Werner Sommer & I dug and found piece of cast iron and added "iron"

1973 I found iron pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 16, 1998 1/2" galv. pipe 6" deep on north side of piece of cast iron 14" deep which is on the north side of pointed stone 19" deep. Replaced the 1/2" galv pipe with 5/8" X 3' re-rod with Lenawee County Remon cap stamped P.S. 13040 and set monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

5/8" X 3' re-rod with a Lenawee County Remon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner

Fd. small round hd. spike in Elec. pole N 45° E 42.51
Fd. small round hd. spike in Elec. pole West 38.72
Cut "X" on CMP S 45° E 30.49
Cut "X" on CMP S 50° W 34.51
Stone at C-1, T7S-R5E West 21.55 with galv. pipe 0.5 W. of stone

W. of stone

Of Michigan

GLENN E.
RICHARD

No. 13040

Charles

Date 11-3-98

Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Manchard Date 11-3-98
	1/2 10 100

Glenn E. Richard

Surveyor's Michigan License No. 13040

Date *Nov. 10, 1998*