REMONUMENTATION

LIBER 001 PAGE 62

APR 28 1995

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

Lenawee	Located in:	Corner Code #	TILE	
(County)	Located III.	Comer Code #	1	om
1. Public Land Survey	T <u>- 6 - S</u> R <u>- 5 - E</u> T R T R T R	<u>K - 13</u>	DEC 29 1994 LENAWEE COUNTY JEANSTTE D. KNOX REGISTER OF DEEDS	3:51PM
in Section S 3. Miscellaneous S	TR TR TR TR		Register of Deeds Stamp &	
			A B C D E F G	HIJKLM
4. Lot No, Recorde 5. Private Claims	<u> </u>		3 4 7 8 9	3 2 1 10 11 12
I, Glenn E. Richard do hereby certify that under requirer in lines 1 and 2 above were in con- current manual of survey instructions Management or by a decree of a Cou- above were in conformance with the Court of Law; established, re-es- expressed below:	ments of P.A. 74, Michigan nformance with regulations s of the United States Dep art of Law and/or that the c e rules of the Michigan Boa	s and rules therefore as require partment of the Interior, Bureau comer points mentioned in lines 3 ard of Land Surveyors or by a De	entioned 7 ed in the 8 of Land , 4 and 5 ecree of a 10 30 29 28 2	15 14 13 22 23 24 27 26 25 34 35 36
NOTE: Not more than 4 corner on this certificate.	s, all in the same town	and range, may be recorded	13	
G.L.O. June 1819, Jose Found no record of t July 1980, We dug 12' in December 1966 and a small piece of strap iron pipe.	eph Fletcher set post this corner ever being ± Easterly (no occup d an 80 year old land iron driven in the bo	owner told me that the sottom of a wood stake, point in L. 4, P. 347. NE. cor. of NW. cor. of NE. cor. of NE. cor. of	E 23, Elm 8 N 27 W 24. uly 1980. t corner of Section 2, T7S-R5E, v SE. corner of Section 35 was 12 leces of brick and two small ste	± East. We foun
December 2, 1994, I d	lug and found the 1/2		establishing corner: e iron pipe and dug hole to se stake. Set 30" Harrison monum	
30" Harrison monume as the best available NE. corner of Section NE. Cor. garage \$ 10 NW. Cor. porch \$ 60	ent stamped P.S. 1304 evidence of the posit n 2, T7S-R5E, West 11. 0° W 130.52 0° W 90.25 (Aluminum ° W 74.00 (Aluminum)	40 and is accepted tion of the original corne 23 siding)	e locating the position of the corn	ENN E. HARD

Ratified by Peer Group in accordance with P.A. 345
Signed by Signed by Rehard Date_December 22, 1994_ Clenn E. Richard

Surveyor's Michigan License No. <u>13040</u>

Signed by_

SSIONAL SU