## SURVEY & REMONUMENTATION

JAN 1 5 1998

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1979BER 1 PAGE 205

## SECTION

For corners in			
Lenawee (County)	Located In:	Corner Code #	STATE OF MICHIGAN
,			LENAWEE COUNTY FILED
Public Land Survey	T <u>-7 - S</u> R <u>- 4 - E</u> T R T R	M - 5	17 OCT 97 3:53 P.H.
2. Property Controlling S in Section S	T		VICTORIA J. DANIELS REGISTER OF DEEDS
3. Miscellaneous S Property in Sec S	T R		Register of Deeds Stamp & File Number
4. Lot No, Record	ded Plat		A B C D E F G H I J K L I
1, Glenn E. Richard , in a field survey on September 04,19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			ed 6 18 17 6 15 14 13 nd 7 15 8 19 20 21 22 23 24
expressed below:			10 30 29 28 27 26 25
NOTE: Not more than 4 cor on this certificate.	ners, all in the same tov	vn and range, may be recorded	12 31 32 33 34 35 36

Description of original monument and accessories and/or subsequent restoration;

G.L.O. 1819 Joseph Fletcher, set post cor. Sec. 12 & 13 Lynn 12 N 21 W 19 Sugar 12 S 31 E 23 1890 James Blair found the old stake

Early 1900's J.L. Richard records "Iron & stones" and same witnesses as Blairs

J.L. Richard Found drag tooth placed tile over same

1968 I dug and found a tile and rust spot in the sub soil where the iron had been and set iron pipe 1973 K.L. Suydam found iron pipe and recorded it in L 2 P 391

1981 I found the iron pipe which checked the one 1968 witness and recorded it in L 5, P20.

Blairs record distance between M-4 & 5 is 2650.56 Measured 2651.18.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Sept. 4, 1997 I found the iron pipe and replaced it with a 3/4" X 3' iron pipe capped G.E.R. 13040

Sept. 5, 1997 Set monument box after Len. Co. Rd. Comm. layed new asphalt pavement.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E.R. in monument box and is accepted as the best available evidence of WANTER HARMAN the position of the original corner. MICHIGA

Found dbl hd nail & disc in 40" Ash N 30° W 58.33 Found dbl hd nail & disc in 26" Maple (stump) N 80° E 24.88 Found dbl hd nail & disc in 30" Maple S 25° W 111.23 Found dbl hd nail & disc in 30" Maple West 24.32 3/4" iron pipe in monument box @ A-5 T7S R5E North 3.96

BYONAL SU Hern Chiclard Date Sept. 30, 1997 Ratified by Peer Group in accordance with P.A. 345

Date Oct 7,199 Glenn E. Richard

Surveyor's Michigan License No., 13040

OF

GLENN E.

RICHARD

No. 13040