JAN 1 5 1998

Filed under Remonumentation Act 345 of 1990LIBER 1 PAGE 228

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN LENAWEE COUNTY

For corners in			LITED
Lenawee (County)	Located In:	Corner Code #	22 DEC 97 9:23 A.H.
1. Public Land Survey	T <u>-8-S</u> R <u>-2-E</u> T R T R		VICTORIA J. DANIELS REGISTER OF DEEDS
Property Controlling in Section S Miscellaneous S Property in Sec S	T R T R T R T R T R R T R R T R R T R R T R R T R R T R R T R T R R T		Register of Deeds Stamp & File Number
4. Lot No, Record	led Plat		2 3 5 3 2 3
I, Glenn E. Richard do hereby certify that under require in lines 1 and 2 above were in co current manual of survey instruction Management or by a decree of a Co above were in conformance with th Court of Law; established, re- expressed below:	informance with regulations and ins of the United States Depart out of Law and/or that the come in rules of the Michigan Board on the Michigan Board or the Board or t	nd rules therefore as required in the intent of the interior, Bureau of Lander points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of	the ind 7 d 5 8 19 20 21 22 23 24 of a as 9 10 30 29 28 27 26 25
NOTE: Not more than 4 corr on this certificate.	ners, all in the same town	ı and range, may be recorde	d 11 32 33 34 35 36 13
A. Description of original mo	nument and accessories a	nd/or subsequent restoration:	
G.L.O. 1824 Ziba S	wan Set 1/4 section pos	st Hick 16 S 12 1/2 W 19 E	Beech 26 N 15 1/2 E 23

1871 Burton Kent "found 1/4 post to correspond with the witness trees, the stumps of which were found standing"

1880 James Blair "Found 1/4 post"

1918 J. L. Richard RLS No. 171 records call for "stone found"

1972 Tim Mohr under my direction dug and found large stone 1.5 deep and raised with 3/4" X 4" iron pipe.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dec. 11, 1997 Found 3/4" X 3' iron pipe on west side of 4" X 5" X 22" square cut stone Dug out the iron pipe & stone and set 30" Harrison monument at location of iron pipe and reset the stone along the east side of the harrison monument.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison monument stamped P.S. 13040 and is accepted as a careful and faithful perpetuation of the position of the original corner.

Found dbl. hd. nail in E.P. N 80° E 112.74 Found dbl. hd. nail & disc in fence post South 24.17 Survey mark spike & re-mon disc in 4" Oak S 5° W 34,91 Survey mark spike & re-mon disc in 8" Basswood Dbl. hd. nail & disc in E.P. N 80° W 167.14



	A STATIONAL SHEET
Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Signed by Slenne Cockard Date 12-	Glenn Richard Date December 16, 1997
Glenn E. Richard Surveyor's Michigan License No. 13040	FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871 REVISED MAY 14, 1875
	REVISED JAN., 1983