

Filed under Remonumentation Act 345 of 1990 1 PAGE 141

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

300	17 B B	4 60 60	15

MAY 1 6 1997

For corners in	•	and the second second							
Lenawee	Located In:	Corner Code #		٠.	CT.	ልቁሮ ጠር	RIPH	7012	
(County) 1. Public Land Survey	T <u>-8-\$</u> R <u>-5-E</u>	_C- 13				ate of Lenave F			
·	TR TR TR				3 1	DEC 96	3:1	8 P.H.	
2. Property Controlling in Section	S T R S T R		Regis	iter of	JI Deeds	EANETTI STATE			nber
3. Miscellaneous Property in Sec	STR STR						`		< L M
4. Lot No, 5. Private Claims	Recorded Plat		1 2 3		5	4	3	1	
			4 5		8	9	10-	11	-12
	, in a field st		9 96, 6	18	17	16-	15	14	13-
in lines 1 and 2 above we current manual of survey in	r requirements of P.A. 74, Michigan Pere in conformance with regulations structions of the United States Depa	and rules therefore as required arment of the Interior, Bureau of	d in the 8	19	20	21	-22	23	24
above were in conformance Court of Law; establishe	e of a Court of Law and/or that the co with the rules of the Michigan Boar of re-established, monumented, r	rd of Land Surveyors or by a Dec	cree of a 10] 7	29-	28	27	26	25-
expressed below:			12	2 31	32	33	-3 4	35	-36-
NOTE: Not more than a on this certifica	4 corners, all in the same town a te.	and range, may be recorded	13	, L	.L	—			
	-								

A. Description of original monument and accessories and/or subsequent restoration:

1820 Joseph Wampler set post corner Section 33 and 34 Elm 9 S 50 E 8 Sugar 10 N 11 E 16 1891 James Blair found stone.
1909 Survey by Charles Keating, Co. Surveyor, called for stone.
Early 1900's J.L. Richard records call for stone
June 1971 We dug and found wood stake surrounded by tile and stones and raised with a 3/4"X4' iron pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

June 10, 1996 Found 3/4" iron pipe in pavement which checked the two remaining witnesses. July 8, 1996, Set 3/4" X 3' gas pipe capped G.E.R. 13040 in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' gas pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the orginal corner.

Dbl. hd nail and Re-mon tag in E.P. N 45° W 44.47 Dbl. hd nail and Re-mon tag in E.P. S 70° E 148.47

"X" cut on S. end C.M.P. N 10° E 145.67

G-12, T8S-R5E, North 2694.50

NE corner Section 4, T9S-R5E, East 114.67

GLENN E.
RICHARD
No. 13040

	$\alpha / \alpha / \alpha = 0$
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Dan Chicker Date 7-16-96
Sel as la	

Glenn E. Richard
Surveyor's Michigan License No. <u>13040</u>

Date 10-11-95

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971