MAY 1 8 1297

and for the first of the

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	• .	•	LENAWEE COUNTY
Lenawee	Located In:	Corner Code #	FILED
(County)			3 DEC 96 3:23 P.H.
Public Land Survey	T <u>-9-\$</u> R <u>- 5 - E</u> T R T R	<u>E-1</u>	JEANETTE D. KNOX REGISTER OF DEEDS
in Section	S T R S T R		Register of Deeds Stamp & File Number
3. Miscellaneous Property in Sec	S T R S T R	***************************************	
· · · · · · · · · · · · · · · · · · ·	ecorded Plat		1 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5
in lines 1 and 2 above were current manual of survey inst	, in a field strength of P.A. 74, Michigan in conformance with regulations tructions of the United States Depot a Court of Law and/or that the conformations in the conformation of the United States of Law and/or that the conformation of Law and/or the conformatio	s and rules therefore as required partment of the Interior, Bureau of	entioned 7 and in the 8 19 20 21 22 23 24 of Land
above were in conformance	with the rules of the Michigan Boa, re-established, monumented,	ard of Land Surveyors or by a Dec	pund as 11 32 33 34 35 36
NOTE: Not more than 4 on this certificate	corners, all in the same town 3.	and range, may be recorded	13
A. Description of origin	nal monument and accessories	s and/or subsequent restoration	on:

GLO 1820 Joseph Wampier set post at intersection corner Section 4 & 5, Sugar 9 S 69 W 5, Sugar 12 S 84 E 15 Early 1900's J.L. Richard record "stone, drag tooth & crockery" and road plans (surveyed by J.L. Richard) on file at the Lenawee County Road Commission show the corner as being 2.8' East of centerline P.I. 1987, I set an iron pipe 33 feet East of the drag tooth, found and recorded for E-13, T8S-R5E.

The J.L. Richard "stone, drag tooth & crockery" is probably the record taken during the road survey. Couldn't find any other reference of anyone ever finding this or using it on a survey.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.

May 22, 1996, I used the stationing shown on the road plans and dug through the pavement and found a 5" X 7" X ? stone. I drilled 12" into the stone & cemented in a 1/2" re-bar. Didn't find any trace of a drag tooth or crockery. After reviewing all of the information at two peer group meetings the group rejected the stone I found because I couldn't find any record of anyone ever finding the stone (except on the road survey) or using it on any property surveys and approved the corner as being 33 feet East of the corner recorded for E-13, T8S-R5E in L. 4, P. 67. November 20, 1996, found iron pipe as set in 1987 which is 1.40 South and 5.14 East of the stone I found in May 1996. Set 3/4" X 3' gas pipe capped G.E.R. in monument box 33.00 East of E-13, T8S-R5E and on line between E-13 and F-13, T8S-R5E.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

3/4" X 3' gas pipe capped G.E.R. P.S. 13040 in monument box and is accepted as the best available MINIMUM OF MICHIGAN evidence of the position of the original corner.

SW. corner of house foundation N 65° E 181.85

SE. corner of house foundation S 35° W 178.70

NE. corner of house foundation S 50° W 134.09

Fd. dbl. hd. nail & disc in Elec. pole N 10° W 31.52

3/4" gas pipe in monument box (E-13, T8S-R5E) West 33.00

Co. Rep. Mans Pichael Date 10-29-1996 Ratified by Peer Group in accordance with P.A. 345 Date Nov. 27, 199 (

Glenn E. Richard Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

STATE OF MICHIGAN

GLENN E. RICHARD No. 13040

SONAL SUF