

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N.R. SW


1005 COUNTY

DESCRIPTION OF CORNER Section corner location to Sta. 4-5-1-9

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap buried in sand 1 foot from

DATE MONUMENT PLACED AND WITNESSED 10/25/63

WITNESSES TO CORNER..... 10" Barbed Wire (NW) 100' SW 51' W.



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

100' SW 51' W. Barbed Wire (NW) 100' SW 51' W. to
center of pipe corner.

SURVEYOR'S SEAL

SIGNED Billy O. Buckler DATE 10/25/63
REGISTERED LAND SURVEYOR