

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 26-27-34-35

CORNER MONUMENT 1" pipe with 1/4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 6-11-69

WITNESSES TO CORNER..... 10" Hard Maple (S35 NBT) S68°E 19.1'



9" Hard Maple (S27 NB T) N24°W 23.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from a Hemlock stump bottom, bearing N34°W 63 links and in an old N-S fence line.  
Found old blazes on trees and logs to east.  
Distance checks well to an original corner, 1/2 mile south.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler,  
Billy D. Buckler DATE 7-25-69  
REGISTERED LAND SURVEYOR