

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 45N R 9W

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 25-36

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 12-16-68

WITNESSES TO CORNER..... 8" cedar (1/4S NBT) S70°E 13.0'



9" cedar (1/4S NBT) N15°E 21.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in middle of old E-W grade. Found iron pipes bearing N45°W and S45°E for witnesses.
Found old fenceline running north from corner.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 4-21-69
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68