

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 20-21-28-29

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-31-69

WITNESSES TO CORNER..... 6" B. Cherry (S 28 NBT) S32°E 31.4'



6" B. Cherry (S 29 NBT) S51°W 12.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at location of several old squared stakes. Found no evidence of original corner.

Corner lies 15' south of intersection of roads to north, east and west, bordering a spruce plantation.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Bally D. Buckler  
REGISTERED LAND SURVEYOR

DATE 1-26-70