

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 28-29

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-31-69

WITNESSES TO CORNER..... 9" Hard Maple (1/8 NBT) S52°W 11.9'



14" Hard Maple (1/8 NBT) North, 31.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established, midway and on line between two Sec. Cors.  
Found old wood post lying on ground at corner, but found no original evidence.

Corner lies 185' north of road.

SURVEYOR'S SEAL

*Billy D. Buskler*  
SIGNED Billy D. Buskler DATE 1-26-70  
REGISTERED LAND SURVEYOR