

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 31-32

CORNER MONUMENT 1" pipe with 4" aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7-10-69

WITNESSES TO CORNER..... 9" W. Pine (1/4 S NBT) S4°E 16.5'



12" W. Pine (1/4 S NBT) N45°W 26.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. Cors.
Found no evidence of original corner.
Corner lies 15' south of woods road.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 1-26-70
REGISTERED LAND SURVEYOR