

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 29-30-31-32

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7-10-69

WITNESSES TO CORNER..... 12" W. Pine (S30 NBT) N83°W 61.5'



12" W. Pine (S 32 NBT) S14°E 11.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed from one possible Hemlock B.T.

Position checks well with corners in all four directions.
Found a very old line of blazes along mile to north.
Distance east to swamp checks well.

REPLACES CORNER DATED 6/25/69

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 1-26-70
REGISTERED LAND SURVEYOR