

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 9-10W


Luce COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 25-30

CORNER MONUMENT 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED 4-25-69

WITNESSES TO CORNER..... 12" Jack Pine (¼S NBT) S23°W 27.7'



4" Red Pine (NBT) N20°W 13.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. Cors. Found no evidence of original corner.

Corner lies 25' north of plantation corner and in planting.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8-28-69
REGISTERED LAND SURVEYOR