

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 10W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 24-25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-29-69

WITNESSES TO CORNER..... 10" W. Birch (NBT) S20°E 20.7'



11" W. Pine (1/2 S NBT) S75°E 80.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies 50' east of woods road.

This corner re-established midway and on line bet. two Sec. Cors.
Found no evidence of original cor.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler,
Billy D. Buckler
REGISTERED LAND SURVEYOR DATE 8-28-69