

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 44-45N R 10W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 4-5-32-33

CORNER MONUMENT 2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 4-16-69

WITNESSES TO CORNER..... 9" Cedar (S33 NBT) N47°E 25.0'



9" Cedar (NBT) N84°W 8.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as placed by unknown surveyor. Found 2" iron pipe in place, with several cedars blazed, facing the corner. Corner lies east of center line M-117.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Billy D. Buckler
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

5-2-69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing