

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N.R. 10W

Luce


COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 25-26-35-36

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-14-69

WITNESSES TO CORNER..... 11" Hard Maple (S 36 NBT) S73°E, 16.0'



10" Hard Maple (S35 NBT) S74°W, 24.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown person.

Found 1" iron pipe in place. Found blazes on trees to east and South approx. 20 years old. Found a rotted stump bearing NW from corner to conform with position of record witness, which was a 9" Y. Birch.

Cor. lies on top of a hardwood hill.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 3-6-70  
REGISTERED LAND SURVEYOR