

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 10W


Luce COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ corner bet. Secs. 25-36

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-14-69

WITNESSES TO CORNER..... 10" W. Pine ($\frac{1}{4}$ S NBT) S12°E 6.9'



CIRCLE CORNER REGISTERED

9" W. Pine ($\frac{1}{4}$ S NBT) S58°E 22.7'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old wood post, origin unknown. Position agrees with corners $\frac{1}{4}$ mile and $\frac{1}{2}$ mile west. Found no evidence of original corner or witnesses. Found remains of hemlock stumps in vicinity. Corner lies on west edge of an old skid road.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 3-6-70
REGISTERED LAND SURVEYOR