

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N.R. 10W


Luce COUNTY

DESCRIPTION OF CORNER West 1/16 Corner bet. Secs. 25-36

CORNER MONUMENT 1" iron pipe

DATE MONUMENT PLACED AND WITNESSED 8-14-69

WITNESSES TO CORNER..... 13" hard maple (W 1/16 BT) N34°W 9.6'



7" hard maple (W 1/16 BT) S25°W 27.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown persons.

Found iron pipe in place with remains of old wood post lying on ground and several blazes on nearby trees.

Corner lies in hardwood, on north slope of hill.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3-6-70  
REGISTERED LAND SURVEYOR