## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 45N N.R. 10W Luce COUNTY DESCRIPTION OF CORNER \_ # Cor. bet. Secs. 19-30 CORMER MONUMENT In pipe with 4" aluminum cap. DATE HONUMENT PLACED AND WITHESSED \_\_ 12-4-69 9" B. Cherry (4S NBT) N70°E 83.11 WITHESSES TO CORNER..... AND CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by single proportionate measure between two section corners.

Found no evidence of original corner.

Corner lies in an open field, 42' west of a meandering fence.

SURVEYOR'S SEAL

Buckler DATE 8-29-70 SIGNED