

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 10,11W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 19-30-24-25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7-31-67

WITNESSES TO CORNER..... 10" Soft Maple (S25 MBT) S84°W 27.0'



16" Soft Maple (S30 MBT) S42°E 32.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as set by unknown surveyor.  
Found 2" wellpoint with two old wood posts, standing at corner.  
Corner lies at bottom of south edge of a ridge, in low, hemlock, hardwood land.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 11-27-70  
REGISTERED LAND SURVEYOR