## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 Luce Go.

FOR CORNERS OF -:	LOCATED IN-:	I-II CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	т. <u>45</u> <b>х</b> , к. <u>10</u> <b>ў</b> .	I-10	
2. PROPERTY CONTROLL- ING IN SECTION——	N. E.		
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO , RECO	RDED PLAT		-
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
the corner points mentioned in field survey on	lines 1 and 2 above (idea 1969), established in conformance with regulited States Department of that the corner points mound, recovered, restored, established.	ntified with circles on index d, re-established, monumente ulations and rules therefore as the Interior, Bureau of Land I tentioned in lines 3,4 and 5 testablished or re-established	code diagram — over) were, in a d, re-monumented, recovered or sequired in the current manual Management or by a decree of a above were, in a field survey or as expressed below and in con-
A. Description of original monu I-11 Gorner 26-27-34	ment and accessories and F-35, placed by Ma.	or subsequent restoration:  Ives, D.S. in 1849.	
1419 ( Ger. bat. Sec	es: 26-27 set by 4.	lves, D.S. in 1849.	
B. Description of corner eviden I=11 Corner re=estr		plied in restoring or re-establ , one mile North and c	
I-10   Corner re-esta	blished midway and	on line be <b>t. two Sec.</b>	C <sub>ors</sub> .
C. Description of monument for Placed 1" pipe with 4	corner and accessories e	established to perpetuate loca	ting the position of the corner:
I-11 Rew Witnesses		W 35.9' and 10" h.	Maple N71°W 30.0'
1-10 New Witnesses:	13" H. Maple S36°	E 43.8' and 9" H. M	apla \$62 <sup>0</sup> W 35.51
SIGNED BY Silly D. Buc	illy to Buckle	DATE	3/5/23
SURVEYOR'S MICHIGAN REGI	,		(SEAL)
FOR STATE AND UNITED STA	* <del>************************************</del>	Three set stores and a second	The compact that is a substitute of the compact that is a substitu
SIGNED BY.	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY.	MICHIGAN RÉGISTÉRED L'AI	NÓ SURVEYŐĞ DATE	