## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

1 Corner

FOR CORNERS OF -:	f	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY T	. 45 X., R. 10 X.	M-8	
2. PROPERTY CONTROLL- ING IN SECTION, T	N. E. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION, T	N. S., R. W.		
4. LOT NO	D PLAT		
5. PRIVATE CLAIMS		:	REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in lines 1 re-established, monumented, re-monumented in the Bureau of Land Management or by a and 5 above were, in a field survey on as expressed below and in conforman Decree of a Court of law:	and 2 above were, in a fice intented, recovered or restore courrent manual of survey decree of a court of law.	ored as expressed below and instructions of the United State Furthermore, that the corner of the United State of the United St	, 19 70, established, in conformance with regulations tes Department of the Interior, points mentioned in lines 3, 4 ed, established or re-established
A. Description of original monument	and accessories and/or sul	bsequent restoration:	
M-8 Quarter Corner on Ea Bearing were: Birch	stside of Section ? 11. S42 <sup>0</sup> W. 14 lks.	74, set by Wm Ives, D.S. and Birch 13, N68 E.	S. in 1849. 22 lks.
B. Description of corner evidence for M-8 Gorner restored midways			
C. Description of monument for corr	per and accessories establish	ned to perpetuate locating the p	osition of the corner:
M-8 Placed 1" pipe with	4" aluminium cap at	corner.	
New Bearings: 12" R Corner lies 36' West	. Pine, S64 <sup>0</sup> W, 46 of road.	5.3' and 8" R. Pine, 1	N55°W. 54.7'.
SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGIST FOR STATE AND UNITED STATE	RATION NO. 8887	DATE_ <b>9-14-7</b> 0	BUCKLER LAND SURVEYOR NO. 18887
SIGNED BY	IEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY		DATE	
			(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.