## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

3 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PULLIC LAND SURVEY	N. 1 S., R., W.	
2, PROPERTY CONTROLL- 36 ING IN SECTION-	.1. 45 N. R. 10 K.	2,6,7
3, MISCELLANEOUS PROPERTY IN SECTION	,T. S., R E.	
4. 1.01 NO. , RECO	PRDED PLAT,	
5, PRIVATE CLAIMS		

- A. Description of original monument and accessories and or subsequent restoration:
- East 1/16 corner between Sec's. 25-36.
- Northeast 1/16 corner of Sec. 36.
- North 1/16 corner on East side of sec. 36.

Corners were not prev. est.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- . Former set midway and on line between section corner to Dast and 1/4 corner to West.
- Ocrner set at intersection of North-South and East-West lines from 1/16 corners North, South, East, and computated 1/16 corner to West.
- 7 Corner set midway and on line between section corner to North and 1/4 corner to South.

( Description of monument for corner and accessories established to perpetuate locating the position of the corner: laced 1" gipe with 4" deptt. cap at all three corners. Fearings are:

- 2 90 Cherry, S52°W, 48.21 & 5" R. line, N68°W, 53.41 & 18" W. Fine Stump, N32°W, 30.81.
- $_{\rm c}$  = 12 W. line,  $576^{\rm o}$ W, 22.05 % 10 W. Fine,  $520^{\rm o}$ M, 39.4 % 10 M. Fine,  $550^{\rm o}$ E, 33.4 .
- 7 Par Hemiock, S62'E, 60.0' & 10" P. Marte, S16'W, 27.8' & 6" R. Naple, N66'W, 10.0'.

SIGNED BY Kavil B Babb

DATE 10-20-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOF STATE AND UNITED STATES AGENCIES