

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 14-15-22-23

CORNER MONUMENT 2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 8-12-69

WITNESSES TO CORNER..... 9" H. Maple (S23 NBT) S84°E 26.4'



8" H. Maple (S15 NBT) N53°W 44.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as placed by H. Lawrence, R.L.S. Found iron pipe in place with two pipes set as witnesses, bearing: N45°W, 45.0' and S45°E, 45.0'. Corner lies 12.0' north of woods road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3-6-70
REGISTERED LAND SURVEYOR