

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER ¼ corner bet. Secs. 15-22

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-12-69

WITNESSES TO CORNER..... 6" Hard Maple (¼S NBT) S82°E 14.6'



10" Hard Maple (¼S NBT) S54°W 30.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established, midway and on line between two Sec. Cors.
Found no evidence of original Cor.

Corner lies 6' north of E-W road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3-6-70
REGISTERED LAND SURVEYOR