

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER 4 Corner bet Secs. 35-36

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-2-67

WITNESSES TO CORNER..... 12" Hard Maple (4S NBT) N60°W 15.3'



10" Hard Maple (4S NBT) S2°W 12.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established at intersection of old road to north and east.

Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED *Billy E. Buckler*
Billy E. Buckler
REGISTERED LAND SURVEYOR

DATE 12-2-70