

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER West 1/16 corner bet. Sees. 21-28

CORNER MONUMENT 2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 8-12-69

WITNESSES TO CORNER..... 13" hemlock (W 1/16 BT) S15°W 7.2'



9" Cedar (W 1/16 BT) East 26.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as placed by H. Lawrence, R.L.S.  
Corner lies in swamp and in NW corner of recent timber cutting.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler DATE 3-24-70  
REGISTERED LAND SURVEYOR