## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		Lace	COUNTY
	т	44,-4,5N	R 11W
DESCRIPTION OF CORNER Sec. Cer. cemmen to Sec	ss. 2-3-34-35	<b>i</b>	
CORNER MONUMENT 1" pipe with 4" aluminum cap.	•		
DATE MONUMENT PLACED AND WITNESSED 7-26-67			
WITNESSES TO CORNER 6" cedar (S35 NBT) No	59°E 4.21		
N 5" cedar (S2 NBT) S72	5 <sup>®</sup> W 120°	· · · · · · · · · · · · · · · · ·	
45-11 AND			
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an eld cedar post with all four eriginal witnesses in evidence; a W. Pine bearing, N79°E 19 lks, page broken off about 3° high; three cedar stumps, cut 16° high bearing N50°W 5 lks, S35°W 23 lks, and S45°E 24 lks. Found eriginal faces with scribe marks on all stumps. Corner lies in a thick cedar swamp.

SURVEYOR'S SEAL

SIGNED

Silly G. Buckler.

Brily D. Buckler

3-27-69

DATE

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor

Forestry Div., Lansing