

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 23-26

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 8/21/67

WITNESSES TO CORNER..... 9" Hard Maple (1/4S NBT) S 62°W 20.8'



8" Hard Maple " S 23°E 11.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Section Corners.

No evidence of original corners.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR

DATE 10/26/67