

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N. R. 11W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 24-25

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 8/21/67

WITNESSES TO CORNER..... 15" Hard Maple (1/4S NBT) S29°E 30.7'



9" Hard Maple (1/4S NBT) S50°W 41.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established, midway and on line between two Section Corners.

Found no evidence of original corner.

Found some old blazes in vicinity.

Corner lies $1\frac{1}{2}$ chains East of a log road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

10/26/67