

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 14-23

CORNER MONUMENT 1" x 18" Iron, buried in road

DATE MONUMENT PLACED AND WITNESSED 8/21/67

WITNESSES TO CORNER..... 15" Elm (1/2 S MBT) S7° E 18.0'



12" Hard Maple " S38°W 34.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in East - West road, 33.0' South of a Fence Corner. Found an old wood post on south side of road and several blazes on trees.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 10/26/67
REGISTERED LAND SURVEYOR