

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 45N R 11W

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 27-34

CORNER MONUMENT 1 1/2" x 30" pipe buried in E-W road

DATE MONUMENT PLACED AND WITNESSED 7-27-67

WITNESSES TO CORNER..... None available



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner replaced midway bet. two fence corners to north and south.
Fences are 50' apart. Distances to other corners and fences in area check well.**

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

3-27-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing