

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

18.


Luce COUNTY
T 45N R 11W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 21-22-27-28

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-10-67

WITNESSES TO CORNER..... 5" Cedar (S22 NBT) N1°W 21.4'



4" Cedar (S21 NBT) N51°E 8.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established using a corner, ridges, fences to south; a Sec. corner, one mile north; swamp edges, etc. to east and west. Found remains of a tamarack in proper location but no definite evidence of a witness tree. Corner lies in an extremely thick cedar swamp.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

3-27-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing