

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 20-21-28-29

CORNER MONUMENT 2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 8-12-69

WITNESSES TO CORNER..... 8" cedar (S29 NBT) S62°W 25.4'



8" hemlock (S28 NBT) S26°E 12.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as placed by H. Lawrence, R.L.S. Found pipe in line with old fence to west and north. Also, found two pipes set as witnesses, bearing, N45°W, 45.0' and S45°E, 45.0'.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3-24-70  
BILLY D. BUCKLER  
REGISTERED LAND SURVEYOR