

**SURVEY &
REMONUMENTATION**

APR 07 1998

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

SECTION Luce County Remonumentation Corner

- For corners in
- | | | |
|------------------------------------|-------------|---------------|
| Luce County | Located in: | Corner Code # |
| 1. Public Land Survey | T45N R11W | C-3 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

LUCE COUNTY
REGISTER OF DEEDS
Recorded
Liber 3 Page 766
02-24-1998 14:44:41
Kathy S. Mahar, Register
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

William L. Karr, in a field survey on December 12, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-3) Section Corner Common to Sections 5, 6, 7 and 8, T. 45 N., R. 11 W.

1849 William Ives set post in original survey.

Witnesses: 10" Sugar N 48° E 36 lks
7" Sugar S 62° W 37 lks

Could find no subsequent survey history on this corner in available public records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-3) Section Corner Common to Sections 5, 6, 7 and 8, T. 45 N., R. 11 W.

This corner is being perpetuated as part of the Luce County Remonumentation Program.

Could find no evidence of the original corner or subsequent restoration.

Reestablished corner by double proportionate measurement between the section corner 1 mile West and the 1/4 corners 1/2 mile North, South and East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-3) Section Corner Common to Sections 5, 6, 7 and 8, T. 45 N., R. 11 W.

Corner is a 1/2" x 48" re-bar with a stamped aluminum Luce County Remonumentation cap. The corner falls in a wooded area.

Witnesses: Steel Fence Post North 1.00'
6" Maple N 08° E 50.68'
8" Maple N 84° E 33.68'
10" Yellow Birch S 52° E 17.02'
10" Maple S 53° W 17.20'

Bearings are compass bearings, corrected for declination (6°W), all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by William L. Karr

Date 12/22/97

Surveyor's Michigan License No. 27450

