

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N.R. 12 W


Luce COUNTY

DESCRIPTION OF CORNER East 1/16 Corner, Section 29

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/10/65 Distances in Feet

WITNESSES TO CORNER..... 18" Hard Maple (E 1/16 BT), N 36° E, 11.0'



9" Hard Maple (E 1/16 BT), West 29.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner placed in fence Corner with fences bearing ~~N-S-E~~ and West.
Found this fence corner to be 1320' West of the East side, Sec. 29.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler.
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 3/24/1966