

# LAND CORNER RECORDATION CERTIFICATE

**FILING REQUIREMENT OF ACT 74, MICH. P.A.1970**

Luce Co.

1 Corner.

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>45</u> <sup>N.</sup> <del>S.</del> , R. <u>12</u> <sup>E.</sup> <del>W.</del>	<u>K-1</u>
2. PROPERTY CONTROLLING IN SECTION _____	, T. _____, S., R. _____, E., W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____, S., R. _____, E., W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-9, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

**K-1** Section Corner between Section's 1-2 on North boundary of Township, set by Wm A. Burt, D.S. in 1841.  
Bearings were: Birch 12", N56°E, 51 lks. and Beech 28", N85°W, 23 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**K-1** Re-witnessed corner as set by unknown Surveyor many years ago.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**K-1** Found 1" Iron Bolt in place; 3.0' South of an East-West fence. Bolt stands 3" above ground level.


New Bearings: 10" W. Ash, S54°E, 3.5' and 10" H. Maple, N75°W, 8.4'.

SIGNED BY \_\_\_\_\_

*Billy D. Buckler*

DATE 9-23-79

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_