Luce County Remonumentation Program

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

1993

For corners in	i inig ricquii		IN 1919
Luce	Located in:	Corner Code ##	Flod 62 /22 A.D.; 19 93
Public Land Survey	T <u>45N</u> R <u>12W</u> T R T R	<u>A-9</u>	At 10:00 o'clock A
Property Controlling in Section Miscellaneous Property in Sec.			Luce County Reg, of Deeds Register of Deeds Stamp & File Number
5. Private Claims Milliam L. Karr do hereby certify that under requirements 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance with Court of Law, established, reexpressed below:	in a field survey on Novemi uirements of P.A. 74, Michigan P.A. conformance with regulations ar ctions of the United States Depai Court of Law and/or that the corn in the rules of the Michigan Board e-established, monumented, re-	ber 19, 93 of 1970, the corner points ment of rules therefore as required rtment of the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decremonumented, recovered, four	2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 12 13 14 13 14 13 14 13 15 14 13 15 14 13 16 15 14 13 16 16 16 16 16 16 16 16 16 16 16 16 16
on this certificate.	nonument and accessories an	nd/or subsequent restoration	12 31 32 33 34 35 36 13 13 1

(A-9) Section Corner Sections 19 & 30, T45N-R12W and Section Corner Sections 24 & 25,

T45N-R13W (Range Line and County Line)
1841:Corner est. by J. Burt for W.A. Burt:A cedar 12" diameter. Cedar 15 N38W 7 links S 64 W 23 links N 52 E 48 links 1849: Guy H. Carleton added 2 Bearing Trees: Cedar 12

White Birch 12

1974: Champion International: Section 19 sketch shows blazed witness Cedar (Lawrence) and two witness pipes.

1984: Thomas O'Brien, L.S. 21274. Corner recorded in Pg. 370 of Luce County Corner Records. Found 1 1/2" iron pipe - checks well to stream crossing South.

10" Cedar S 47 W 38.2' 6" Cedar S 46 E 59.7' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner reestablished as part of the Luce County Remonumentation Program. Found a 2" O.D. pipe, 30" above ground and the two record ties as recorded by O'Brien. Found a 2" O.D. pipe, 30" above ground that bears N43°E - 89.82' from recorded corner. Midway between pipes found a 2" O.D. x 30" pipe, pinched on each end, lying on the ground (knocked out by fallen tree) and a fallen 12" Cedar with old blazes (no scribing). Believe witness corner pipes were set by County Surveyor J. Kinsey. In my opinion, O'Brien used the Witness Corner pipe in the Southwest quad for the Section Corner. Reestablished corner position midway and on line between found witness corner pipes. Stump of fallen Cedar bears N20°W, 9' from reestablished corner position. Note: An 18" Cedar is on line between the Section Corner and the Witness Corner pipe in the Northeast quad.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 1/2" x 48" iron with a 3 1/4" diameter stamped aluminum cap, 4" above ground.

15" Cedar	N08°E	29.69'	
2" O.D. Pipe (18" Cedar on Line)	N43°E	44.91'	
17" Cedar of Twin	N76°E	26.13'	
14" Maple	S66°E	76.10'	
2" O.D. Pipe (O'Brien Rec. Cor.)	S43°W	44.91'	
9" Yellow Birch	M ₀ 08 <i>M</i>	63.43'	

Date .

Signed by 27450 =Surveyor's Michigan License No. _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 LOD - Distances Revised May 14, 1975

NOTE: Bearings are compass bearings corrected for declination. Distances are to a nail with P.S. 27450 tag in side of witness objects unless noted.

REVISED JAN., 1983

KARR LAND **JRVEYOR**