

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luce COUNTY


T 46N R 9W

DESCRIPTION OF CORNER South 1/16 Cor. bet. Secs. 8-9

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/11/71

WITNESSES TO CORNER..... 12" Tamarack S53°W 72.6'



10" Cedar N19°E 106.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed midway and on line bet $\frac{1}{4}$ Cor. to north and Sec Cor. to south.

Corner lies in wet open marsh 70ft. south of e-w timber line.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

12/17/71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68