

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 46N R 9W

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. Sec 8-9

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/11/71

WITNESSES TO CORNER..... 8" Hemlock S74°E 50.2'



8" Cedar S70°W 36.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies on top of NW-SE ridge. 90ft. south of E-W skidding road.

Corner re-established midway and on line bet. two Sec. Cors. Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 12/17/71
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68