

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 8-9 W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 6-7-1-12.

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 12-12-69

WITNESSES TO CORNER..... 10" Cedar (S6 NBT) N20°E 32.2'



12" Hemlock (S8 NBT) S85°E 21.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one Hemlock B.T., a stub, bearing N 32°E, 25 Links. Upper face is in excellent condition with most scribe marks plain.

Corner lies 40' south of a woods road.

Corner found by William Botti; Area Forester.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 1-12-70