

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY  
T 46N R 9W

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs 16-17

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/18/71

WITNESSES TO CORNER..... 12" Cedar N44°E 14.7'



8" Cedar North 26.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established midway and on line bet. two original Sec. Cors.

Found no evidence of original corner or Spruce witnesses.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 1/7/72  
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing *e*

R 4047  
Rev. 10/68