

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46-47N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 3-34

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 2-13-62 with L. Rubick, Aide

WITNESSES TO CORNER..... 5" Tamarack ($\frac{1}{4}$ S NBT) N70°W, 13 links



4" Tamarack ($\frac{1}{4}$ S NBT)(omitted) , 54 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two section corners. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 26, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler