

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 9. W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 8, 9, 16, 17 . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . . . .

WITNESSES TO CORNER 10" Red Pine . . . N 68° W . . . 77½ links . . . . .

12" Red Pine . . . N 30° E . . . 88 links . . . . .

-----

-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Yellow Pine B.T. in good condition.

Corner is on South edge of narrow ridge E - W.

Corner shown to us by J. Halbach, District Forester.

Corner placed and witnessed March 14, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 3/19/56  
REGISTERED LAND SURVEYOR