

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N. R. 9 W.


Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 16, 17, 20, and 21

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 11/4/60 with D. Bonner, Ass't. D.F. and

WITNESSES TO CORNER....12" Cedar (NBT S 20) S 67° W 24 1/2 Links



7" Cedar (S 17 NBT) N 25° W 25 Links

9" Cedar (S 2 NBT) S 21° E 26 Links

AND

(9" Cedar Stump (NBT) N 22° E 29 Links by H. Lawrence)

CIRCLE CORNER REGISTERED

### DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Cedar bearing Tree (Stub) bearing N 12° W, 23 Links. In Good condition. Found post set by H. Lawrence, Registered Surveyor. Corner lies 1/2 chain south of ridge in swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7/14/61  
REGISTERED LAND SURVEYOR  
Billy D. Buckler