

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 46 NR 10 W

Luce

COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 4-9

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 6" Soft Maple (clump) S 22° E 153 links

No other witnesses available

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 corner midway and on line between two section corners.

Found^{no} evidence of original corner.

Placed turned, creosoted post at corner.

Corner placed and witnessed December 4, 1957.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 12/4/57
REGISTERED LAND SURVEYOR